

Dear K2 Snowboarder,

We are writing to inform you of the immediate recall of our 2007 model year K2 “Auto” series snowboard bindings. The decision to recall the product is the result of reports of the strap cable breaking on this binding. If the strap cable were to break while riding, it could potentially cause the rider’s boot to become loose or release from the binding causing a loss of control. This recall does not affect any other K2 binding products.

Please stop riding your 2007 model year K2 “Auto” series snowboard bindings immediately and bring them back to the shop where they were purchased. The strap cable will be replaced for free. If you are in the USA and are not able to visit the dealer where you purchased the Auto binding, please contact K2 at 800-985-2191 or send an email to [AutoBindingUpgrade@k2sports.com](mailto:AutoBindingUpgrade@k2sports.com) for instructions.

K2 has a 20-plus year history of designing safe, convenient, and high-performance snowboarding products that make the sport more fun for all levels of riders. We stand behind our products and pride ourselves on our relationship with our customers. Please accept our apologies for this inconvenience.

Sincerely,

K2 Sports

This recall is in cooperation with the U.S. Consumer Product Safety Commission, who will monitor the effectiveness of this recall program

If you are outside of the USA, please use the following contact information:

	PHONE	EMAIL
CANADA	1-877-393-7049	
JAPAN	03-3320-7822	
EUROPE (GENERAL)	+49 8856 901 172	autobinding@k2sports.de
NORWAY	+47 61 13 43 00	madshus@madshus.com
UK	+44 (0) 1527 510570	gail@k2-uk.co.uk

If your AUTO bindings look like this, please stop riding them immediately and contact K2 to get them UPGRADED

If your AUTO bindings look like this, they are UPGRADED and you are good to go riding!

